

General Environmental Incident Summary

Incident: 3377 **Date/Time Notice:** 7/8/2014 1015 **DEM Incident No:**

Responsible Party: David Peyer

Date Incident: 7/8/2014 **Time Incident:** 1515 **Duration:**

County: Williams **Twp:** 156 **Rng:** 95 **Sec:** 32 **Qtr:**

Lat: 48.28452 **Long:** -102.92370 **Method:** Interpolation from map

Location Description: 1.6 miles east of the intersection of State Highway 8 (60th St NW) and State Highway 21 (105th St NW) in Williams County, ND.

Submitted By: Bridget Sedlack

Affiliation: Gibson Energy, LLC

Address: 3819 Towne Crossing Blvd

Suite 100

City: Meaquite

State: TX

Zip: 75150

Received By:

Contact Person: Dave Peyer

870 36th Ave NW

Cole Harbor, ND 58531

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Unloading Hose failed

Description of Released Contaminant: Crude Oil

Volume Spilled: 10.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Driver stated he had all of his valves open and started pumping off when his hose suddenly blew off the end of his fitting.

Risk Evaluation:

None.

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

None.

Action Taken or Planned:

Driver contained release with spill kit. Environmental clean up company also sent a cleanup crew out to do the cleanup. Removed impacted soils for proper disposal.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 7/8/2014 ***Status:*** Reviewed - No Action Required

Author: Roberts, Kris

Updated Volume:

Notes:

Release due to unload hose damage. Description of incident and quick response by driver and follow-on cleanup crew makes on-site inspection unnecessary.